

## DESCRIPTION

This concrete cleaner and etcher is specially formulated for use on concrete floors, brick, masonry block, and flagstone. It contains powerful muriatic acid to clean, etch, and whiten concrete and neutralize surface alkalinity. It should be used to prepare all concrete surfaces before painting or sealing, and to provide maximum penetration, bonding strength and durability of the coating.

## DANGER POISON

MAY BE FATAL IF SWALLOWED. CAUSES SEVERE BURNS. VAPOR HARMFUL. Do not inhale or swallow. Keep away from skin, eyes and clothing. Wear rubber gloves and eye protection when handling. Use with adequate ventilation. Do not mix with any other chemical.

### FIRST AID:

**IF IN EYES:** Flush eyes and under eyelids with water for at least 15 minutes. Obtain medical attention.

**IF ON SKIN:** Wash with soap and water. Remove contaminated clothing and launder before reuse. If irritation is persistent, contact a physician.

**IF SWALLOWED:** Contact physician or poison control center immediately. Do not induce vomiting. Drink large quantities of water.

**IF INHALED:** Move person to fresh air. Obtain medical attention.

See M.S.D.S. for complete safety information.

**KEEP OUT OF REACH OF CHILDREN**

**HANDLING AND STORAGE:** Keep container tightly closed when not in use. Do not store in unmarked containers. Use plastic containers to mix solutions - do not store in metal pails, drums or sprayers. Keep away from alkaline materials, metals and metal salts. Rinse empty container before disposal.

# TOTAL SOLUTIONS™

RESILIENT FLOOR CARE

## CONCRETE CLEANER & ETCH

Cleans, Etches and Bleaches

• PROVIDES IDEAL SURFACE PREPARATION BEFORE SEALING OR PAINTING

• CLEANS, ETCHES AND BLEACHES IN ONE STEP

**KEEP OUT OF REACH OF CHILDREN**

## DANGER POISON

MAY BE FATAL IF SWALLOWED.  
CAUSES SEVERE BURNS.  
VAPOR HARMFUL.

See side panel for additional precautions.

NET CONTENTS:

5  6  20  30  55 Gallons

Manufactured By: Total Solutions™  
PO Box 240014 • Milwaukee, WI 53224

## DIRECTIONS

Sweep floor to remove loose soil. For heavily soiled floors, scrub with a strong detergent to remove heavy soil, grease and oil deposits and rinse. Etch the surface by using a solution of 1 gallon of this product in 5 gallons of water. Swab solution onto the surface, and scrub with an old broom or brush. Allow to work for 10 minutes or until bubbling and fizzing stops. Rinse the surface thoroughly with clean water and allow to dry completely before sealing or painting.

Rinse empty containers before disposal. Use plastic containers to mix solutions. Do not store in metal pails, drums or sprayers.

**This Product Contains/CAS Number:** Water/7732-18-5; Hydrochloric Acid/7647-01-0; Poly (oxyethylene) nonylphenol/9016-45-9; Ethoxylated Amine Resin/61790-47-4; Green Dye/61791-17-1.

NFPA® RATINGS  
FLAMMABILITY

HEALTH  REACTIVITY

0140.050311